## CASE STUDY:

## NATIONAL CONVENIENCE STORE

LOCATION: NEWPORT, NEW HAMPSHIRE

## SITUATION:

The customer had an aging EPDM roof that was installed incorrectly and as a result, was rapidly deteriorating. The previous roofing provider did not rust strip the surface, which caused the membrane to pull and develop severe wrinkles.





**SR 454 MA** 



SAM (Self Adhered Modified) sheet with Wite Brite™ and Poly



## **SOLUTION:**

Simon Roofing identified the cause of the issue with a comprehensive SR PreVision inspection and analysis. After cutting, stretching and re-fastening the old EPDM membrane to remove the wrinkles, we installed our SAM (self-adhered modified) system over the existing membrane. Our unique process of liquid-applying Wite Brite<sup>TM</sup> and embedding Poly within the Wite Brite<sup>TM</sup> layers resulted in a watertight roof with a new, full 15-year warranty.

