


# CASE STUDY: Big Box Retail Store

LOCATION: Redding, CA



## SITUATION:

This big-box retail store was experiencing 60+ roof leaks across the facility. The leaks were creating slip-and-fall hazards for both customers and employees, as well as damaging inventory and impacting customer experience. They wanted a watertight solution, but a long-term option was not desired as there were plans to move from this location in a few years.

 1,269 sq. ft.

 SR 521-05a Metal Restoration



## SOLUTION

After a thorough inspection and learning the goals of the facility, Simon Roofing identified a restoration solution for the metal roof. The SR 521 restoration solution was installed with a five year warranty. In addition, Wite Brite Colors was applied around the skylights for safety reasons. All roof leaks are resolved and the roof was brought back to watertight condition for a fraction of the cost of a replacement.



## END RESULT:

- Customized solution to meet building goals
- Watertight condition with 5 year warranty
- Warranty covers both labor and materials
- Improved rooftop safety with skylight identification

